



9205 CROSS CONNECTOR

INSTALLATION INSTRUCTIONS




BEGIN BY POSITIONING TOWERS APPROXIMATELY 90"
APART WITH MOUNTING FLANGES FACING IN.


MAKE SURE TOWERS ARE LEVEL AND FLAT ON GROUND
AND FACING DIRECTLY TOWARDS EACH OTHER




POSITION CONNECTOR BETWEEN TOWERS
AS SHOWN



SECURE CROSSMEMBER USING (QTY 2)
1/2"-13 X 1 1/2" BUTTON HEAD SCREWS,
WASHERS, AND NYLOCK NUTS





MAKE SURE ALL HARDWARE IS TIGHT AND
TEST ALL FUNCTIONS BEFORE OPERATING
EQUIPMENT

